

20W Solid State Power Amplifier 6-18GHz



Features

- Psat: + 43.5dBm
- Gain: 51 dB
- Supply Voltage: +36V
- 50 Ohm Matched
- Short Haul / High Capacity Links
- Military & Aerospace Applications



Electrical Specifications, TA = +25°C Vcc = +36V

	1						
Parameter	Min.	Тур.	Max.	Min.	Тур.	Max.	Units
Frequency Range		6 ~ 12		12 ~ 18		GHz	
Gain		52		51		dB	
Gain Flatness		±5			±4		dB
Gain Variation Over Temperature (-45 ~ +85)		±3			±3		dB
Input Return Loss		15 13			dB		
Output Return Loss	25 22			dB			
Saturated Output Power (Psat)		43			43		dBm
Supply Current (Vcc=+36V)		2.0			2.0		Α
Isolation S12		65			65		dB
Max Input Power (No Damage)	Р	Psat - Gain Psat - Gain			dBm		
Weight	3000 g				g		
Impedance	50 Ohms					Ohms	
Input / Output Connectors		SMA-Female					
Power / Control Connector		D-sub COMBO 3POS					
Finishing	Standard: Nickel 220 micron thickness						
Material		Aluminum / Copper					
D. I C. II	Epoxy and Screw tight Sealing (Standard)						
Package Sealing	Hermetically Sealed (Option with extra charge)						

^{*} P1dB, P3dB and Psat power testing signal: 200µs pulse width with 10% duty cycle.

^{*} For average CW testing, power must be backed off by 5dB from Psat is required unless water/oil cooling system is applied.



Absolute Maximum Ratings				
Supply Voltage	+40Vdc			
RF Input Power (RFIN)	Deat Cain			
Pin_max = Psat - Gain	Psat - Gain			
Storage Temperature (°C)	-50 to +125			

Note: Maximum RF input power is set to assure safety of amplifier. Input power may be increased at own risk to achieve full power of amplifier. Please reference gain and power curves.

Biasing Up Procedure				
Step 1	Connect Ground Pin			
	Connect input and output with 50 Ohm			
Step 2	source/load.			
	(VSWR<1.9:1 or >10dB return loss)			
Step 4	Connect +36V biasing			
Power OFF Procedure				
Step 2	Turn off +36V biasing			
Step 3	Remove RF connection			
Step 4	Remove Ground.			

Environmental Specifications				
Operational Temperature (°C)	-45 ~ +85			
	(Case Temperature must be less			
remperature (c)	than 85C at all times)			
	30,000 ft.			
Altitude	(Epoxy Seal Controlled			
	environment)			
	60,000 ft 1.0psi min			
	(Hermetically Seal Un-controlled			
	environment)			
	(Optional)			
Vibration	25g RMS (15 degrees 2KHz)			
	endurance, 1 hour per axis			
Humidity	100% RH at 35c, 95%RH at 40°c			
Shock	20G for 11msec half sine wave,			
	3 axis both directions			

Note: The operating temperature for the unit is specified at the package base. It is the user's responsibility to ensure the part is in an environment capable of maintaining the temperature within the specified limits.

Ordering Information					
Part No.	Description				
RFLUPAo618GB	3A001.b.4.b.4	6GHz~18GHz Power Amplifier			

Amplifier Use

Ensure that the amplifier input and output ports are safely terminated into a proper 50 ohm load before turning on the power. Never operate the amplifier without a load. A proper 50 ohm load is defined as a load with impedance less than 1.9:1 or return loss larger than 10dB relative to 50 Ohm within the specified operating band width.

Power Supply Requirements

Power supply must be able to provide adequate current for the amplifier. Power supply should be able to provide 1.5 times the typical current or 1.2 times the maximum current (whichever is greater).

In most cases, RF-Lambda amplifiers will withstand severe mismatches without damage. However, operation with poor loads is discouraged. If prolonged operation with poor or unknown loads is expected, an external device such as an isolator or circulator should be used to protect the amplifier.

Ensure that the power is off when connecting or disconnecting the input or output of the amp.

Prevent overdriving the amplifier. Do not exceed the recommended input power level.

Adequate heat-sinking required for RF amplifier modules. Please inquire.

Amplifiers do not contain Thermal protection, Reverse DC polarity or Over voltage protection with the exception of a few models. Please inquire.


Proper electrostatic discharge (ESD) precautions are recommended to avoid performance degradation or loss of functionality.

What is not covered with warranty?


Each of RF-Lambda amplifiers will go through power and temperature stress testing. Due to fragile of the die, IC or MMIC, those are not covered by warranty. Any damage to those will NOT be free to repair.




Gain vs. Frequency




Input Return Loss



Isolation



Output Return Loss





Note: Input/output return loss measurements include attenuators to protect equipment




The power beyond expectations

Gain vs. Output Power







P7dB vs. Frequency









2nd Harmonic Wave vs. Pout



3rd Harmonic Wave vs. Pout




4th Harmonic Wave vs. Pout







Alarm Status Panel:




	Name	Function	Initial State	Description	Applied
	RESET	Control		Manual reset button to reset PA	Yes
LED 1	POWER	Indicator	RED Color	LED will light to <u>RED</u> color when supply power is applied	Yes
LED 2	RF IN	Indicator	GREEN Color	PA will shut down and latch this LED to a <u>RED</u> color when input signal is over limit *	Yes
LED 3	VSWR	Indicator	GREEN Color	PA will shut down and latch this LED to a RED color when output reflection is over limit *	Yes
LED 4	ID	Indicator	GREEN Color	PA will shut down and latch this LED to a <u>RED</u> color when an imbalance in the drain current of the combining branches occurs or if a drain current limit is reached *	Yes
LED 5	TEMP	Indicator	GREEN Color	PA will shut down and latch this LED to a <u>RED</u> color when driven over temperature *	Yes


*LED needs to be manually reset to initial state by pressing RESET button



Amplifier Outline Drawing:

All Dimensions in mm [inches]






Heat Sink and cooling fan required during operation





Air Cooling Outline Drawing:

All Dimensions in mm [inches]



Important Notice

The information contained herein is believed to be reliable. RF-Lambda makes no warranties regarding the information contained herein. RF-Lambda assumes no responsibility or liability whatsoever for any of the information contained herein. RF-Lambda assumes no responsibility or liability whatsoever for the use of the information contained herein. The information contained herein is provided "AS IS, WHERE IS" and with all faults, and the entire risk associated with such information is entirely with the user. All information contained herein is subject to change without notice. Customers should obtain and verify the latest relevant information before placing orders for RF-Lambda products. The information contained herein or any use of such information does not grant, explicitly or implicitly, to any party any patent rights, licenses, or any other intellectual property rights, whether with regard to such information itself or anything described by such information.

RF-Lambda products are not warranted or authorized for use as critical components in medical, life-saving, or life sustaining applications, or other applications where a failure would reasonably be expected to cause severe personal injury or death.